



# MST GROUP LTD (HK)

## Final Random Inspection Report

ADD: UNIT 710, 7F, BAOLI BUILDING, NANHAI ROAD, NANSHAN DISTRICT SHENZHEN, P.R. CHINA 518054  
 Tel: 86-755-26421993      FAX: 86-755-26429496      Email: info@mstradechina.com      Website: www.mstradechina.com

### EXECUTIVE SUMMARY AND INSPECTION STANDARD:

Client:	MST Group	Contact person:	×××××					
PO.No.:	H-SCS-080201	Description:	Plough machine					
Supplier:	××××××	Contact person:	Cathy					
Insp. Location:	××××××	Time of insp.:	1 <sup>st</sup>	✗ 2 <sup>nd</sup>	3 <sup>rd</sup>			
Order No.	Item No.	Order Qty	Available Quantity			inspect Qty		
			Packed	Not packed	Not finished			
H-SCS-080201		120	20	100	0	120pcs		
<b>Inspection standard:</b> <i>ANSI/ASQC Z1.4-1993</i> Sampling plan: <i>Single, Normal</i> Inspection level: II AQL: Critical: Not Allowed.					<b>Sample Size: 120pcs</b>			
					Critical	Major	Minor	
					<b>AQL:</b>	<b>0</b>	<b>1.5</b>	<b>4.0</b>
					<b>Defects Found:</b>	<b>0</b>	<b>0</b>	<b>4</b>
					<b>Max. Allowed:</b>	<b>0</b>	<b>5</b>	<b>10</b>
<i>Sample carton No.: No carton No. for available.</i>								

### Overall conclusion

Inspection criteria	Result	Comments
Quantity available:	<input checked="" type="checkbox"/> conformed [ ] not conformed	
Workmanship:	<input checked="" type="checkbox"/> conformed [ ] not conformed	
Test:	<input checked="" type="checkbox"/> conformed [ ] not conformed	
Data measurement:	<input checked="" type="checkbox"/> conformed [ ] not conformed	
Labeling:	<input checked="" type="checkbox"/> conformed [ ] not conformed	
Packing/shipping mark:	<input checked="" type="checkbox"/> conformed [ ] not conformed	
<b>Result:</b>	<input checked="" type="checkbox"/> <b>Acceptable</b> [ ] <b>Reject</b> [ ] <b>Pending</b>	
<b>Special remark:</b>		

Inspector signature: Yu Xinjiang      Date: Feb 18, 08      Vendor signature: \_\_\_\_\_ Date: \_\_\_\_\_

This report only reflects the truth of quality in this lots goods, based on statistical sampling procedure. Inspection is performed to the best of our ability and skills but without responsibility on our part, nor does it evidence shipment. [www.mstradechina.com](http://www.mstradechina.com)



**MST GROUP LTD (HK)**  
**Final Random Inspection Report**

ADD:UNIT 710,7F,BAOLI BUILDING,NANHAI ROAD, NANSHAN DISTRICT SHENZHEN, P.R.CHINA 518054  
Tel: 86-755-26421993      FAX: 86-755-26429496      Email:info@mstradechina.com      Website:www.mstradechina.com

*INSPECTION RESULT IN DETAILED:*

**WORKMANSHIP:**

Item No.	Check Qty	Defects Description	Cri	Maj	Min
	120pcs	Scratch mark on surface, not smoothly.			1
		Dirty mark on surface.			1
		Tough face.			1
		Unable to return to exact position.			1
<b>Total defect:</b>			<b>0</b>	<b>0</b>	<b>4</b>
<b>Allowed:</b>			<b>0</b>	<b>5</b>	<b>10</b>
<b>Result:</b>			<b>PASSED</b>		



## MST GROUP LTD (HK) Final Random Inspection Report

ADD: UNIT 710, 7F, BAOLI BUILDING, NANHAI ROAD, NANSHAN DISTRICT SHENZHEN, P.R. CHINA 518054  
Tel: 86-755-26421993      FAX: 86-755-26429496      Email: info@mstradechina.com      Website: www.mstradechina.com

### TEST AND MEASUREMENT:

Test items	Sample size	Result	Comments
Product dimension:		[ ] conformed [ ] not conformed	Overall size: N/A
Carton drop test:		[ ] conformed [ ] not conformed	N/A
Power on test:		[ <input checked="" type="checkbox"/> >] conformed [ ] not conformed	<u>gasline engine 6.5L</u>
Battery test:		[ ] conformed [ ] not conformed	<u>N/A</u>
Launching test:	<b>3pcs</b>	[ <input checked="" type="checkbox"/> >] conformed [ ] not conformed	<b>3 Seconds, ok.</b>
velocity changing	<b>3pcs</b>	[ <input checked="" type="checkbox"/> >] conformed [ ] not conformed	<b>3 Seconds, ok.</b>

### LABEL CHECKING:

Label	Result	Comments
(Small part) warning label:	[ ] conformed [ ] not	N/A
Price label:	[ ] conformed [ ] not	N/A
“Made in china”:	[ ] conformed [ ] not	N/A
Barcode label:	[ ] conformed [ ] not	N/A
UL / CE / customer Logo.	[ ] conformed [ ] not	N/A
Customer label.	[ ] conformed [ ] not	N/A

### PACKING AND ACCESSORIES

**1). Master carton:(shipping mark please reference to attach picture) N/A**

Item No.:	Master shipper ( pcs/ctn )	Carton size L×W×H (cm)	G.W (Kgs)	N.W (Kgs)	Product Barcode	Carton Barcode
	1	83 x37.5 x 77cm	78	75	-	-

### PRODUCT AND DEFECTS PHOTO SHOW

<p align="center"><b>Master carton view:</b></p>	<p align="center"><b>Main marking:</b></p>															
																
<p align="center"><b>Side mark:</b></p>	<p align="center"><b>Open carton view:</b></p>															
 <table border="1" data-bbox="370 1192 646 1276"> <tr> <td>Модель</td> <td>Посадка</td> <td>шт</td> <td>Вес брутто</td> <td>кг</td> </tr> <tr> <td>MO443</td> <td>75</td> <td></td> <td>78</td> <td></td> </tr> <tr> <td>Габариты(мм)</td> <td colspan="4">630*375*170</td> </tr> </table>	Модель	Посадка	шт	Вес брутто	кг	MO443	75		78		Габариты(мм)	630*375*170				
Модель	Посадка	шт	Вес брутто	кг												
MO443	75		78													
Габариты(мм)	630*375*170															
<p align="center"><b>Instruction sheet:</b></p>	<p align="center"><b>Tools for assembly:</b></p>															
																
<p align="center"><b>Spare parts:</b></p>	<p align="center"><b>Metal frame for packing:</b></p>															



Side of metal frame:



Side of metal frame:



Side of metal frame:



Product after assembly:



Side of product:



Sticker on oil tank:



Sticker on machine:



Sticker on the metal frame:



Sticker on shield board:



sticker on the cover of the transfer band:



front of the machine:



Back of machine:



**Level for left hand:**



**Level for right hand:**



**plough assembled**



**Plough assembly:**



**parts view:**



**Parts view:**



**Parts view:**



**reference No. Of the engine**



**axle of the front wheel:**



**embrace of the front wheel:**



**gear lever:**





**embrace on back of the machine:**



**bottom of the machine:**



**Wheels:**



**test of changing the velocity:**



**launching test:**



**test of the power rating for engine:**



**test of the power rating for engine**



**velocity testing of the transfer band:**



**Tough surface:**



**Dirty mark:**



**unable to return to exact position:**



**scratch mark: (surface not smoothly)**



**Finished products:**



**Packed products:**



**END**